

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT	UNIT TYPE:											
Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Wilson					
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		PERMIT NO.: SLAS-98-08					
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		FILE TYPE: COMPLIANCE					

Date of Site Inspection: $\underline{1/4/2012}$ **Date of Last Inspection:** $\underline{11/3/2011}$

FACILITY NAME AND ADDRESS:

David Newsome D & D Septic LLC 441 Buck Newsome Road Fremont, NC 27830

GPS COORDINATES: N: 35.59874 W: -77.87832

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: David Newsome Telephone: 252-206-6802

Email address: Fax: *252-242-4268*

FACILITY CONTACT ADDRESS:

Same as above.

PARTICIPANTS: Chester Cobb, Michael Scott, and Tony Gallagher

STATUS OF PERMIT: Active EXPIRES: 5/11/2016

PURPOSE OF SITE VISIT: Routine

STATUS OF PAST NOTED VIOLATIONS:

An observed violation to NC Septage Management Rule .0838 a. (1) was noted on the 11-03-11 inspection report. The crop in an approximately 2 acre section of Field 3, withn irrigation Pull #9, had been destroyed when the effluent from a dewatered load of fatty acids had been applied by accident.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. Signage present at the entrance to the dewatering facility and by the path beside Field 3.
- 2. Access road in good shape.
- 3. Markers present.
- 4. All discharges within the field boundaries.
- 5. No application issuses noticed today.
- 6. Rye present on all fields. The crop still struggling within Pull #9 of Field 3.
- 7. No application at time of inspection. pH not checked.
- 8. No objectionable odors noticed.
- 9. No change with any setbacks.
- 10. Records not checked.

Please contact me if you have any questions or concerns regarding this inspection report.

Chester R. Cobb

Regional Representative

Sent on: 8-6-12	Email	Hand delivery	X	US Mail	Certified No. [_]